DATA SHEET

Three Phase Induction Motor - Squirrel Cage

:



Product line		: Premium Efficiency Three-Pl	nase Product code :	14709259	
Frame		: 56C	Cooling method	: IC411 - TE	FC
Insulation class		: F	Mounting	: F-1	
Duty cycle		: Cont.(S1)	Rotation ¹	: Both (CW	and CCW)
Ambient temperature		: -20°C to +40°C	Starting method	: Direct On I	
Altitude		: 1000 m.a.s.l.	Approx. weight ³	: 12.1 kg	-
Protection degree		: IP55	Moment of inertia (J)	: 0.0045 kgr	n²
Output [HP]			0.5		
Poles			6		
Frequency [Hz]		60			
Rated voltage [V]		575			
Rated current [A]		0.781			
L. R. Amperes [A]		4.37			
LRC [A]		5.6x(Code K)			
No load current [A]		0.619			
Rated speed [RPM]		1160			
Slip [%]		3.33			
Rated torque [kgfm]		0.313			
Locked rotor torque [%]		240			
Breakdown torque [%]		330			
Service factor		1.15			
Temperature rise		80 K			
Locked rotor time		46s (cold) 26s (hot)			
Noise level ²		405 (COId) 205 (NOT) 50.0 dB(A)			
	25%	1	00.0 dB(/ ()		
Efficiency (%)	50%		68.0		
	75%	74.0			
	100%	74.0			
	25%		10.0		
Power Factor	25% 50%		0.44		
			0.41		
	75%		0.53		
	100%		0.63		
		Drive end Non drive end	Foundation loads		
Bearing type Sealing		: 6203 ZZ 6202 ZZ	Max. traction	: 27 kgf	
		: V'Ring Without	Max. compression	: 39 kgf	
		Bearing Seal			
Lubrication interval		:			
Lubricant amount		:			
Lubricant type		: Mobil Polyrex EM			
Notes			·		
110163					
This revision roal	aces and cor	cel the previous one which	These are average value	es hased on tosts wi	th sinusoidal
This revision replaces and cancel the previous one, which			These are average values based on tests with sinusoidal power supply, subject to the tolerances stipulated in NEMA		
		shaft end	MG-1.	and tolerances supu	
must be eliminate			WO-1.		
must be eliminate (1) Looking the m					
must be eliminate (1) Looking the m (2) Measured at 2	1m and with t				
must be eliminate (1) Looking the m (2) Measured at (3) Approximate	1m and with t weight subjec	ct to changes after			
must be eliminate (1) Looking the m (2) Measured at (3) Approximate manufacturing pr	1m and with t weight subjec ocess.				
must be eliminate (1) Looking the m (2) Measured at (3) Approximate manufacturing pr (4) At 100% of fu	1m and with t weight subjec ocess.	ct to changes after			
must be eliminate (1) Looking the m (2) Measured at (3) Approximate manufacturing pr	1m and with t weight subjec ocess.		Performed	Checked	Date
must be eliminate (1) Looking the m (2) Measured at 7 (3) Approximate w manufacturing pr (4) At 100% of fu Rev.	1m and with t weight subjec ocess.	ct to changes after	Performed	Checked	Date
must be eliminate (1) Looking the m (2) Measured at ((3) Approximate w manufacturing pr (4) At 100% of fu	1m and with t weight subjec ocess.	ct to changes after	Performed	Checked	Date
must be eliminate (1) Looking the m (2) Measured at 7 (3) Approximate v manufacturing pr (4) At 100% of fu Rev.	1m and with t weight subjec ocess.	ct to changes after	Performed	Checked	Date

This document is exclusive property of WEG S/A. Reprinting is not allowed without written authorization of WEG S/A.

Subject to change without notice





This document is exclusive property of WEG S/A. Reprinting is not allowed without written authorization of WEG S/A.

Subject to change without notice